

QUOTE #	TYPE	Work Scheduled	ASSIGNED TO	INQUIRY DATE	STAGE	DAY COUNTER	CUSTOMER	DESCRIPTION	NOTES
23918	Repair		RDN	8/1/2018	TBQ		PW EH	mag gauge replacement on multiple furnaces	re-work of quote 09215, Pete H asked about this
29418					WIP		Honeywell	2 o ring gaskets	
33518	repair	11/26/18?		11/7/2018	WIP		PW Amercon	PHT2 still HOT	David McG wants our plan of action
09918	Repair	need to pick		3/6/2018	WIP		PW EH	rebrick spare base	Quote sent to Joe Konicki, PO coming from Bernd,
20718	maintenance				WIP		PW EH	6 month PM for Sept/Oct 2018 - 556077, 542287, 542519, 542518, 541924, 541923,	no change to quote, will need verification from PW what BT's are covered. EL to sesnd quote after he
28118	Repair		RL	9/27/2018	WIP		PW EH	ER repair on bell furnace	rec'd bill from RL 7960.00
14717	New Build				WIP		SBD	two (2) new temper 26' long	
02418	Repair	almost done, write PR			WIP		SBD	rebuid of 6 burner hardening furnace - qty = 2; 2 new temper furnaces	per Mike M, wants to make sure these #'s are still good, going into meeting to get approval, 1/22 email
07717	New Build				WIP		SBD	new hardening furnace 18'	with 14717
33918	repair			11/14/2018	Inquiry		US Tsubaki	MTO furnace carbon issue	Bob Beaudet called 11/14, wants someone to come up and inspect and propose fix
31918	new build		RN	10/29/2018	TBQ		Chromalloy	Bell Furnace with retort	referral from Dean Russell, 5% like F23, just smaller. 4 burner, clam shell cover, 5' inside the insulation diameter, 5-6' high, with excess air, new cp and gas flow panel
22618	New Build		RL	7/19/2018	TBQ		Goodrich	another pit furnace	
11818	New Build	check in Q3	RDN	3/1/2018	TBQ		HoloKrome	new belt line/system	DLN mtg 3/20, giving us a headstart. He will be releasing an official RFQ. Probably looking at Q3/Q4
17218	Repair	Fall 2018?	RDN	9/1/2018	TBQ		SBD	this is a reminder to reach out to Mike @SBD about changing tubes in Fall 2018	
33618	repair	43437	RDN	11/12/2018	TBQ		SBD (AJ)	B422 Lindberg elements and tubes	
22918	repair			43306	TBQ		TurboParts LLC	Hubbert oven repair	recd call from Will Adams, waiting on pricing from Hubbert, EL called multiple times, left message 8/15, still waiting on Huppert 8/22. Asking Industronics to quote.8/29 Huppert said we're at the waiting to schedule a confrence call 9/20 EL. Specs coming, Wants to see Idl & Stanley furnaces, F/U on
26918	new build		EL	9/6/2018	Inquiry		Blue Blade Steel	new line for HT razor blades	
25418	Repair		RDN	8/21/2018	Inquiry		Checon	Change over ribbon elements to Glow Bars	Not a rush, EL visited 10/18

QUOTE #	TYPE	Work Scheduled	ASSIGNED TO	INQUIRY DATE	STAGE	DAY COUNTER	CUSTOMER	DESCRIPTION	NOTES
33418	repair			11/12/2018	Inquiry		Checon	change over to starbars	see EL email 11/12/18
24518	New Build		EL	8/10/2018	Inquiry	4	gas fired coating furnace	Jeff Smith - eng cons for client in Europe	EL emailed smith more details, can't reveal anything
31318	repair		RN	10/21/2018	Inquiry		Glen Vincent	50 hp oil fired steam boiler. 10/22 JB emailed andrew at Blake Equip. (no luck finding one online) emailed local boiler companies 10/29	
14718	Inquiry		EL	4/18/2018	Inquiry		Industrial Razor Blade	needs recommendation on heat treater in his area and also wants info on cost of new lead from Prairie - dealer in Canada looking for car bottom. They saw our pic on Prairie's site.	IDL used to do all their heat treating, but since SBD bought them, they need recommendations. Frank
30918	new build		EL	10/18/2018	Inquiry		Park Thermal		
34018	repair		EL	11/15/2018	Inquiry		PW EH	service work on 5 autoclave furnaces	Dennis Anderson from Aztechnology (K&S) called 11/15/18
26118	Repair		RDN	8/21/2018	Inquiry	#REF!	SBD	rebuild of Heat Brand and Lindberg in building	
16718	Repair		EL	5/11/2018	Inquiry	#REF!	Starett	install elements, brick repair	email from Gene 5/10/18, Starett purchasing elements, Noble to install and repair any brickwork. Waiting on elements 9/25
27118	repair	EL to visit	EL		Inquiry		Starrett	Rebrick Ipsen Pit,	Visit Required Eric to visit 10/17. furnace running
11918	Repair		EL		Inquiry		Theis Metals	muffle change	EL is contacting them again 3/26 not ready FU 4/16,
21417	New Build		RN		TBQ		Accurate Braze	new 650 deg f electric oven 65w x 67h x 64d	Specsgiven for quoting 2/26/18, not critical
21818	repair		RL/RN	6/7/2018	TBQ		Allied Sintering	2 Lindbergs need up controls & relining	see 6/11/18 email, Ron can't quote until fall
13818	Repair		RDN	4/9/2018	TBQ		Barden	new door for rotarty furnace	Pictures uploaded,
29218	repair				TBQ		Barden Bearings	Pilot Issue	
34318	demolition				TBQ		Bodycote Worcester	Strip furnace for scrapping	
34418	repair				TBQ		Bodycote Worcester	Bell furnace base, K-Wool and Posts, welding. Dave has the posts	Dave to send a drawing

QUOTE #	TYPE	Work Scheduled	ASSIGNED TO	INQUIRY DATE	STAGE	DAY COUNTER	CUSTOMER	DESCRIPTION	NOTES
30618	repair		EL		TBQ		Consolidated	Turntable repour #31 & 80	Refractory drawing sent by Seth, waiting to hear from Seth on form to pour top.
10818	New Build		RN/RL		TBQ		Customer	price out electric furnace	want to put together pricing sp we can market this EL to visit Aug/Sept 2018, working on pricing, waiting for \$ from Fives and Eclipse, price rec'd from
24218	New Build	43341	EL	8/6/2018	TBQ		Fitchburg Welding	Large Car Bottom, specs given	
34118	repair				TBQ		Hitemco	Pit #4 replace covers, new arms	
34218	repair				TBQ		Hitemco	Pit #1 covers 108" at top	
34518	Repair				TBQ		Holokrome	#1 Inner door seal	
34618	Repair				TBQ		Holokrome	#3 replace rails after #1	
24818	material		RDN	8/14/2018	TBQ		holokrome - greg called 8/14	needs NA pilot burner for flame screen, Ron was to call 8/27	
27818	new build				TBQ		International Ceramic Engineering	4x4x4 1700C 3092F Kiln	Spec sheet sent, F/U 11/5 WFR
32718	repair				TBQ		Lenox SBD	Homotemp PM's	
31418	repair				TBQ		Micro Abrasives	Ceramic Mill Relining, EL visited 10/26	Customer has the lining, we need to provide pure portland cement. Quote stripping and installing seperatley. Waiting for decision, do we want to do
31718	new build				TBQ		MikroSystems	box furnace 40x36x36 kiln 4 profile	
14218	New/Repair		RL/RN	4/13/2018	TBQ		Minteq	Canaan, CT lead came in from Ray, Ron	Richard/Rick McDole 860 824 5435, they want a
18618			RL		TBQ		Okay Industries	EL and RL visited 6/14/18; this is all Ron work,	Has honeywell chart recorders to update & tie into per Ray 10/2 budget \$ 175K, emailed PW requesting details, no reponse as of 10/5, EL to follow up F/U
28018	new build				TBQ		Pratt	700F oven	

QUOTE #	TYPE	Work Scheduled	ASSIGNED TO	INQUIRY DATE	STAGE	DAY COUNTER	CUSTOMER	DESCRIPTION	NOTES
32418	repair				TBQ		Praxair Maine	New Shell box furnace	
32518	repair				TBQ		Praxair Maine	Box furnace PM	
32618	repair				TBQ		Praxair Maine	Pit Furnace PM	
22817	repair	when PHT2 up			TBQ		PW Amercon	brick and gasket repair on PHT #1	damage caused by operator error, to be done at
09518	Repair		RDN	3/2/2018	TBQ		PW EH	soundproofing	DN to update pricing and quote for 2018/ Measure
10318	Materials		RL/JB	3/7/2018	TBQ		PW EH	spare flame safety panel	JF to ask RDN
33018	Repair				TBQ		Savage	Pacific Temper roller rack	
15618	Repair		RDN	4/30/2018	TBQ		SBD	mag gauge on burnout new line	
33118					TBQ		SBD	Stanley #16 PM	
33218					TBQ		SBD	Stanley #3 & #4 Burner Guards	
23818	Repair				TBQ		Utility Manufacturing	Salt Pot tank brick and castable repairs	sub-contracting for Industronics, quote to Terry
18818	new build		RL/RN	6/11/2018	TBQ		WG PW	new furnace box 5x5x5	rec'd call from Paul Richard, requesting visit, needs
22518	Repair	43446	RDN	7/12/2018	WIP		Alloy Fab	re-brick Lindberg base & bell	need to contact - can we reschedule to week of 15th.
07318	Repair	? Has anyone		2/9/2018	WIP		Consolidated	insulation repair on preheater 10/29 RDN to	quote done, waiting to send with 05318, sent 3/2;
26818	parts		EL		WIP		Doncasters	spark plug for #6 oven	PO given over the phone, spark plugs are here, EL to
11618	New Build			3/16/2018	WIP	less than 50	Hitemco	special tube furnace - update q# 16717 - NOTE this quote does NOT include	Lenny emailed 3/16/18, needs us to update quote, looking at a potential PO coming in April or May,
15418	Repair		JB	4/26/2018	WIP	7	Honeywell	replacement parts for and inspection of lift system for Noble furnace	Fred says the lift system is vibrating, y, EL to send to Kathy, Try to convince them to purchase at next PM.
07917	Repair				WIP		Noble	bringing old furnace up to snuff	need to get pictures of all components and SELL IT!
09717	Maintenance	on hold			WIP		PW Amercon	PHT #1 annual inspection	will be done when PHT 1 can be shut down
13317	Repair	on hold			WIP		PW EH	PHT in EH shroud & elements	pretty sure BT # is 542754, shld hear from Monty
19218	repair				WIP		Smith & Wesson	re-brick large Upton salt bath	emailed quote to John Dean
14617	Repair	when cooler			WIP		SST	stacks for multiple furnaces, hoods &	DC 3/8 8, DC 3/9 5 duct work ; DLN 3/9 4
27218	repair	need to			WIP	2	SST	water cooler frame - will deliver and bill for	